



## 2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
CHPN	110	5	
	111	5	
	210	5	
	211	5	
	3 <sup>rd</sup> fl. entrance area	5	
	322	5	
	326	5	
	309	5	
	310	5	
	311	5	
	313	5	
	314	5	
	315	5	
	308	5	



# UNIVERSITY OF ARKANSAS

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
CHPN	327	5	
	3 <sup>rd</sup> fl. hall study area	5	
	334	5	
	Elevators	3	Stains
	4 <sup>th</sup> fl. hallway study area	5	
	407	5	
	408	5	

Alm8/31/12