

## CARPET CONDITION SURVEY

### Facilities Management (FAMA)

Last Update	Nov 2013	
Room #	Rating	Comments
A100	3	east lobby
A103	3	
A106	3	
A108	4	
A110	2	
A111	2	
A12	2	
A113	2	
A114	2	
A115	2	
B100	3	
B101	2	
B102	3	
B103	1	
B104	3	
B105	2	
B106	3	
B107	1	
B109	3	
B111	3	
B114	3	
B115	3	
B117	3	
B119	3	
B121	2	
B123	2	
B125	2	
C100	3	
C104	3	
C106	3	
C108	3	
C109	3	
C110	3	
C111	3	
C113	3	
C115	3	
C119	3	
C120	3	
C124	3	
C125	3	
CESU 108D	2	stained, matting
CESU 108F	2	stained, matting
CESU 108G	2	stained, matting
CESU 108H	5	
CESU 108I	1	matting

<b>Room #</b>	<b>Rating</b>	<b>Comments</b>
CESU 108J	5	
CESU 108K	5	
CESU 108M	2	matting
CESU hall	2	matting
CESU reception area	2	matting
D100	3	
D101	3	
D102	3	
D103	3	
D105	3	
D107	3	
D109	3	
D110	3	
D111	3	
D112	3	
D113	3	
D114	3	
D115	3	
WIES	2	
AA	3	
AC	2	hallway
BA	3	
BC	3	
CA	3	
CB	3	
CC	3	hallway
DA	3	hallway
DC	3	hallway