



## 2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
SUZM	104	2	
	2 Stairs 1 /201	2	
	202	2	
	203	2	
	205	2	
	S.W. Bottom	2	
	209	2	
	N.E. Bottom	2	
	108	2	
	109	2	
	110	2	
	2 Stairs 2	2	

Alm2016/