

Facilities Management

FY 2015 CARPET CONDITION SURVEY

- 1. WORN OUT- some places worn through to backing, needs replacement.
- 2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
- 3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
- 4. ALMOST NEW- light traffic pattern wear
- 5. NEW OR LIKE NEW- no wear

BUILDING	ROOM#	RATING	COMMENTS
ARKU – Treasurer Office	213	3	Carpet coming up, overall Needs need to be cleaning
	213A	3	
	213B	3	
	213C	3	Carpet coming up
	213D	3	Carpet coming up
	213E	3	
	213G	3	
	213J	3	
	213K	3	
	213M	3	
	213P	3	
	214A	3	
	214B	3	
	214C	3	

BUILDING	ROOM#	RATING	COMMENTS
	214E	3	214E
	214F	3	214F
	Training Area	4	Light wear
	227A	4	Light wear
	IT Area	4	all floors, light wear
	IT Entrance	4	front area, light wear