



## 2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
ENGR	131	5	
	130	5	
	128	5	
	127	5	
	126	5	
	125	4	Light stains
	124	4	A few stains
	123	5	
	122	4	A few stains
	121	5	
	136	5	
	134	5	
	135	5	
	120	4	



# UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
ENGR	211	3	Threads are worn down in main areas
	212	3	Traffic lanes and stains
	213	2	Stains and seams coming up
	214	4	
	215	3	Traffic lanes and under desk has discoloration
	216	3	Traffic lane
	218	3	Traffic lane to table
	219	4	A few stains
	221	3	Threads are worn down in main area
	224*	3	
	224a	3	Worn threads
	224	3	Traffic lanes to desk
	225	3	Stains and traffic lane
	226	4	
	227	2	Seams are obvious, and traffic lanes



# UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
ENGR	228	2	Stains and traffic lane
	229	2	Seams are very visible, traffic lanes to desk, and under desk has discoloration
	230	4	
	231	3	Under desk has discoloration
	232	3	Under desk has discoloration
	233	3	Under desk has discoloration
	209	3	Stains and traffic lanes at entrance
	208	3	A few stains and light traffic lanes
	207	2	Stains and traffic lanes
	205	4	
	203a	3	A few stains
	204	3	Has traffic lanes
	201b	3	Traffic lanes and a few stains



# UNIVERSITY OF ARKANSAS

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
ENGR	201a	2	Discoloration under desk, stains, and traffic lanes
	201	3	Traffic lanes
	328	3	A few stains, under desk is discolored
	329	4	
	334	3	Stains and traffic lanes
	337	3	Stains and traffic lane to desk
	339	3	Discoloration under chairs
	340b	3	Stains and traffic lane
	340a	2	Stains and traffic lane
	340	3	Traffic lanes
	325	3	Traffic lanes
	324	2	Traffic lanes and stains
	323	3	Has traffic lanes
	322	3	Has traffic lanes
	320	5	
	319	3	



# UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
ENGR	316	5	
	318	3	
	315	4	
	312a	4	
	312b	3	A few stains
	312c	4	Light discoloration under chair
	313a	4	
	313b	4	Light discoloration under chair
	313	4	
	314a	3	Traffic lane and stains
	314b	4	
	314c	2	Water damage stains
	314	3	Has traffic lanes
	309	4	
	308	5	
	307	4	Has a few seams showing
	304	4	



# UNIVERSITY OF ARKANSAS

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
ENGR	301	3	Has a few stains

Alm8/31/12