



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

| BUILDING | ROOM # | RATING | COMMENTS |
|----------|-------------------------|--------|----------|
| MUSC | 107 | 3 | |
| | M305 | 4 | |
| | 309 | 4 | |
| | 201 A | 3 | |
| | M201 B | 3 | |
| | M202 B | 3 | |
| | 213 | 3 | |
| | 1 ST HALLWAY | 3 | |
| | 2 ND HALLWAY | 3 | |
| | 3 RD HALLWAY | 3 | |
| | | | |
| | | | |

Alm8/31/12