



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
ASUP 1 st floor	LOBBY	3	
	106	3	
	106B	3	
	106C	3	
	109	3	
	108	3	
	108A	3	
	107	3	
	102	3	
	104A	3	
	104B	3	
2 nd floor	201	3	
	213	3	
	212	3	
	211	3	
	210	3	
	209	3	
	208	3	
	207	3	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
ASUP	206	3	
	204	3	
	203	3	classroom
	214	3	
	215	3	
	216	3	
	217	3	classroom
	218	3	
	219	3	