



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
ENTR	120	5	
	120A	5	
	120B	5	
	120C	5	
	120D	5	
	120E	5	
	120F	5	
	120H	5	
	120I	5	
	120M	5	
	120N	5	
	120O	5	
	120P	5	
	120R	5	
	120G	5	Several cubicles in this area



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
	North Entrance	5	
	South Entrance	5	

Alm2016/