



FY 2015 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear
5. NEW OR LIKE NEW- no wear

BUILDING	ROOM #	RATING	COMMENTS
BAND	hallway	3	showing some wear
	202	4	light wear, office
	library	4	light wear
	205	4	light wear, office
	206	4	light wear, office
	209	4	light traffic wear