



## FY 2015 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear
5. NEW OR LIKE NEW- no wear

| BUILDING | ROOM # | RATING | COMMENTS                    |
|----------|--------|--------|-----------------------------|
| FNAR     | 116    | 3      | noticeable wear under chair |
|          | 103    | 2      | worn under chair            |
|          | 104    | 1      | needs to be replaced        |
|          | 105    | 1      | needs to be replaced        |
|          | 105A   | 1      | needs to be replaced        |
|          | 105B   | 1      | needs to be replaced        |
|          | 120    | 3      | noticeable wear             |
|          |        |        |                             |
|          |        |        |                             |
|          |        |        |                             |
|          |        |        |                             |
|          |        |        |                             |
|          |        |        |                             |
|          |        |        |                             |
|          |        |        |                             |