



## **FY 2015 CARPET CONDITION SURVEY**

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear
5. NEW OR LIKE NEW- no wear

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
GACS	Tony Garretta Wes Opela	4	light wear
	front of accounting	4	light wear
	214 (Ali)	3	still serviceable, under chair
	office across from Ali	3	noticeable wear under chair
	215	3	noticeable wear under chair
	printer area, 2 <sup>nd</sup> fl	4	light wear
	216	4	light wear
	hallway, 2 <sup>nd</sup> fl	4	light wear
	service info	4	light wear