



## 2015 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
HOEC	106	3	PULLED THREADS
	102	3	
	205	4	
	206	3	
	204	4	
	205B	4	
	205D	4	
	205C	4	
	210	4	
	228	4	
	216	4	
	217	4	
	224	4	
	17A	4	



# UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
HOEC	17B	4	
	17C	4	
	17D	4	
	17E	4	
	17F	3	

Alm8/