

## CARPET CONDITION SURVEY

### Health, Physical Education, and Recreation Building (HPER)

Last Update Oct-11

Room #	Rating	Comments
102	1	worn out
102B	1	worn out
102C	1	worn out
103	1	strings, stairs
214	3	worn
215	3	worn
223	4	
223	3	hper fitness
224	4	
225	3	
226	4	
227	4	
228	4	
229	4	
230	3	
231	4	
231A	4	
231B	4	
232	4	
234	4	
237	4	
238	4	
239	4	
240	4	
244	4	
245	4	
306	4	
306A	4	
306B	4	
306C	4	
307B	3	
308	4	
308A	4	
308B	4	
308E	4	
308G	4	
308H	4	
308I	4	
308J	4	
308K	2	under chair
308M	1	worn out
308N	1	worn out
308P	4	
308PP	1	worn out

<b>Room #</b>	<b>Rating</b>	<b>Comments</b>
308Q	1	worn out
308R	4	
308S	1	worn out
308T	2	
308U	1	worn out
308V	3	
308W	2	under chair
308X	2	under chair
308Y	4	
309	4	
310	3	worn
310A	4	
311	4	
316	3	
318	1	worn out
319	4	
321D	1	worn out
321E	3	worn
hallway	110	4