



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
KIMP	102	4	
	105	4	
	113	4	
	117A	5	
	117J	5	
	117L	5	
	201	4	
	203	4	
	205	4	
	209	4	
	213	4	
	214	4	
	301	4	
	305	4	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
	306	5	
	312	4	
	315	5	
	411	3	



UNIVERSITY OF ARKANSAS