



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
KUAF	011	5	
	005	5	
	Entrance-basement	5	
	111	5	
	110	5	
	108	5	
	106	4	
	107	5	
	104	5	
	103	5	
	118	5	
	116	5	
	ELEVATOR	5	
	1 st Floor Entrance	5	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
KUAF	126	5	
	125	5	
	124	5	
	123	5	
	122	5	
	121	5	
	120	5	

Alm2016/