



## FY 2016 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear.
5. NEW OR LIKE NEW- no wear.

BUILDING	ROOM #	RATING	COMMENTS
LISA	100	4	
	101	4	
	102	4	
	103	4	
	104	5	
	106	4	