



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
MCHS	201	1	
	202	2	
	203	2	
	203 A	4	
	203 B	4	
	207	4	
	209	4	
	210	4	
	204	4	
	303	4	
	304	4	
	305 A	4	

Alm8/31/12