



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
MEMH 1 ST FLOOR	108	4	
	103	4	
	102	3	
	105	4	
	108	4	
	102A	3	
	109	3	Classroom
	129	3	
	130	3	Classroom
	114	3	Classroom
	113	3	Classroom
	111B	3	
	111C	3	
	111D	3	
	111E	3	
	111F	3	
	111G	3	
	111H	3	
	111J	3	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
MEMH	111K	3	318 classroom
	111L	3	
	111M	3	
	111P	3	
	111Q	3	
	111R	3	
2 ND FLOOR	213	3	
	216	3	Classroom
3 RD FLOOR	324	3	
	321	3	
	325	3	
	326	3	
	319	3	
	319B	3	
	319C	3	
	319D	3	
	319E	3	