



## **FY 2015 CARPET CONDITION SURVEY**

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear
5. NEW OR LIKE NEW- no wear

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
MLKG	104	5	
	105	5	
	106	5	
	107	5	
	108	5	
	111	5	
	109	5	
	110	5	
	111A	5	
	112	5	