



FY 2015 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear.
5. NEW OR LIKE NEW- no wear.

BUILDING	ROOM #	RATING	COMMENTS
ROSE	201	3	Noticeable wear under chairs
	202	4	Light wear
	203	3	Noticeable wear
	204	4	Light wear
	205	3	Noticeable wear under chair
	206	3	Noticeable wear under chair
	207	3	Heavy wear under chairs
	208	3	Noticeable wear under chairs