

CARPET CONDITION SURVEY

Stonehenge Apartments - building 1 (STH1)

Last Update Oct 2013

Room #	Rating	Comments
1	3	front 3, back 2, could use extraction cleaning
2	3	could use extraction cleaning
3	3	could use extraction cleaning
4	3	could use extraction cleaning
5	3	could use extraction cleaning
6	3	could use extraction cleaning
7	3	back only, could use extraction cleaning
8	3	could use extraction cleaning
9	2	reasonably clean, no stains