



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
STON	G41	3	
	G42	3	
	G43	3	
	G44	3	
	G45	3	
	G46	3	
	G47	3	
	G52	3	
	G54	3	
	F41	3	
	F42	3	
	F43	3	
	F44	3	
	F45	3	
	F46	3	
	F47	3	
	F50	3	LOBBY