



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
TEST	LOBBY	5	
	100	5	
	103	5	
	107	5	
	111	5	
	112	5	
	113	5	
	114	5	
	115	5	
	116	5	
	118	5	
	119	5	
	120	5	
	120A	5	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
TEST	120B	5	
	120C	5	
	201 CLASSROOM	5	
	205	5	
	206	5	
	208 CONF. ROOM	5	

Alm8/3