



## 2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
AGRI 1 <sup>st</sup> floor	110A	3	
	111	3	
	110B	3	
	115	3	Classroom
2 <sup>nd</sup> floor	205	3	
	201	3	
	202	3	
	203	3	
	204	3	
	232	3	
	231A	3	
	231B	3	
	231C	3	
	230	3	
	228	3	
	227	3	
	207	3	
	226	3	
	225	3	



# UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
AGRI	224B	3	
	223	3	
	223A	3	
	222	3	
	221	3	
	220	3	
	220A	3	
	219	3	
	216	3	
	215	3	
	214	3	
	213	3	
	218	3	
	217	3	
	217B	3	
	217C	3	
	217D	3	
	225	3	
	224B	3	
	223	3	
	223A	3	
	222	3	
	221	3	

FAMA 125 • 1 University of Arkansas • Fayetteville, Arkansas 72701 • (479) 575-3851



# UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
AGRI	220	3	
	220A	3	
	219	3	
	216	3	
	215	3	
	214	3	
	213	3	
	218	3	
	217	3	
	217B	3	
	217C	3	
	217D	3	
	217E	3	
	217F	3	
	217A	3	
	217AA	3	
	218A	3	
	218B	3	
	218C	3	
	218D	3	
	218E	3	
	218F	3	
	218G	3	

FAMA 125 • 1 University of Arkansas • Fayetteville, Arkansas 72701 • (479) 575-3851



# UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
AGRI 3 <sup>RD</sup> floor	301C	3	
	330	3	
	332	3	classroom
	301A	3	classroom
	304	3	
	305	3	
	322	3	
	321	3	
	320	3	
	319	3	
	317	3	
	317A	3	
	316	3	
	315A	3	
	315D	3	
	315E	3	