



FY 2015 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear
5. NEW OR LIKE NEW- no wear

BUILDING	ROOM #	RATING	COMMENTS
AGRX	100	5	Like new
	100B	5	Like new
	101	2	Heavy wear
	101A	2	Heavy wear
	102	5	Like new
	104	2	Heavy wear
	105	2	Heavy wear under chair and desk
	106	2	Heavy wear
	106A	2	Heavy wear
	106B	2	Heavy wear
	107	2	Heavy wear
	108	5	Like new
	109	2	Heavy wear under chair
	111	3	Noticeable wear

