



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
ARKA 1 st Floor	104	4	
	105	4	
	106	4	
2 nd Floor	206	4	
	205	4	
	204	4	
	202	4	
3 rd Floor	309	4	
	301	4	
	302	4	
	307	4	
4 th Floor	401	4	
	402	4	
	403	4	
	404	4	