



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
ARMY 1 ST FLOOR	106	4	
	105	4	
	104	4	
	103	4	
	102	4	
	112	4	
2 ND FLOOR	201A	4	
	203	4	
	204	4	Classroom
	205	4	Classroom