



2015 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
DAVH	108	4	light wear
	107	4	light wear
	106	4	light wear
	105	4	light wear
	104	4	light wear
	213	4	light wear
	212	4	light wear
	211	4	light wear
	210	4	light wear
	209	4	light wear
	208	4	light wear
	207	4	light wear
	204	4	light wear
	205	4	light wear
	216	3	noticeable wear under chair

BUILDING	ROOM #	RATING	COMMENTS
DAVH	317	3	noticeable wear under chair
	314	4	light wear
	313	4	light wear
	312	4	light wear
	311	3	noticeable wear under chair
	310	4	light wear
	309	3	noticeable wear under chair
	308	4	light wear
	307	4	light wear
	306	4	light wear
	305	4	light wear
	304	4	light wear
	basement hallway	4	light wear
	005	4	light wear
	By 005	4	light wear