



**FY 2016 CARPET CONDITION SURVEY**

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear
5. NEW OR LIKE NEW- no wear

<b>BUILDING</b>	<b>ROOM #</b>	<b>RATING</b>	<b>COMMENTS</b>
ECEN	Basement	2	
	3 <sup>rd</sup> Floor Hallway	3	
	2 <sup>nd</sup> Floor Hallway	3	
	230	2	
	West Stairway	2	