



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
GRAS	A100	5	
	A110	5	
	A104	5	
	A107	5	
	A106	5	
	B106	5	
	B109	5	
	B102	5	
	B100	5	

Alm2016/