



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
HAPG	609	5	OFFICE
	703	5	
	703 A	5	LOBBY
	703 B		
	703 C		
	703 D		
	709	5	
	710	5	
	711	5	
	712	5	
	713	5	

Alm8/31/12