



FY 2015 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear.
5. NEW OR LIKE NEW- no wear.

BUILDING	ROOM #	RATING	COMMENTS
JTCD	Hallways	4	Light traffic pattern wear
	103	4	Light wear
	105	4	Light wear
	106	5	No wear
	Entrance by 108	4	Light wear
	108	4	Light wear
	115	4	Light wear
	Entrance by 121	3	Noticeable wear
	121	4	Light wear under chairs
	123	4	Light wear
	126	4	Light wear
	Entrance by 128	4	Light wear
	128	4	Light wear
	132	4	Light wear

