



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
MEEG	217	4	
	216	4	
	227	3	Discoloration under desk
	228	2	Traffic lanes are heavy
	212	4	
	210	3	Some stains
	204a	3	Traffic lanes
	204-copy room	3	Traffic lanes
	209	3	Obvious stains where cable cover mat was
	102b	5	
	102c	3	Has traffic lanes
	105	5	
	109e	2	Water damage stains
	109c	2	Traffic lanes and stains

Alm8/31/12