



FY 2015 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear.
5. NEW OR LIKE NEW- no wear.

BUILDING	ROOM #	RATING	COMMENTS
MULN	102	4	Light wear
	Hallway by 104	4	Light traffic wear
	104	4	Light traffic wear
	107	3	Noticeable wear under chairs
	107A	5	No wear
	107B	2	Heavy wear under chairs
	107C	3	Noticeable wear under chairs
	107D	3	Noticeable wear
	1 st Floor Study Areas	3	Noticeable wear under chair
	114B	3	Light traffic wear
	114C	2	Heavy wear under chairs
	114D	3	Noticeable wear under chairs
	123	4	Light wear
	125	5	No wear

BUILDING	ROOM #	RATING	COMMENTS
MULN	126	5	No wear
	Hallways	3	Noticeable traffic wear
	203	4	Light traffic wear
	205	3	Noticeable wear under chair
	206	3	Noticeable wear under chair
	206A	3	Noticeable wear under chair
	208	2	Heavy traffic wear
	212	4	Light traffic wear
	212A	4	Light traffic wear
	213A	3	Noticeable wear under chair
	214A	3	Noticeable wear under chair
	214B	3	Noticeable wear under chair
	214C	3	Noticeable wear under chair
	214D	3	Noticeable wear under chair
	214E	3	Noticeable wear under chair
	214F	2	Heavy wear under desk
	214G	3	Noticeable wear
	214H	4	Light traffic wear
	214J	3	Noticeable wear under chair
	214K	3	Noticeable wear under chair
	215	3	Noticeable wear

BUILDING	ROOM #	RATING	COMMENTS
MULN	216	3	Noticeable wear
	216A	3	Noticeable wear
	216B	3	Noticeable wear under chair
	216C	3	Noticeable wear
	217	5	No wear
	218	4	Light traffic wear
	219	2	Heavy wear under chairs
	220	2	Heavy wear under chairs
	220B	3	Noticeable wear
	220C	3	Noticeable wear
	220H	4	Light traffic wear
	220J	3	Noticeable wear under chair
	220M	3	Noticeable wear under chair
	220N	4	Light traffic wear
	220Q	4	Light traffic wear
	220R	3	Noticeable wear under chair
	221	4	Light wear
	222	3	Noticeable wear under chair
	222B	3	Noticeable wear under chairs
	223A	4	Light traffic wear
	223B	3	Noticeable wear under chair

BUILDING	ROOM #	RATING	COMMENTS
MULN	223C	3	Noticeable wear under chair
	223D	3	Noticeable wear under chair
	223E	2	Heavy wear under chair
	223F	3	Noticeable wear under chair
	224	4	Light traffic wear
	224A	4	Light traffic wear
	224B	3	Noticeable wear under chair
	225	4	Light traffic wear
	226A	4	Light wear
	226B	4	Light wear
	226C	4	Light wear
	226D	3	Noticeable wear under chair
	226E	3	Noticeable wear under chair
	233	4	Light traffic wear
	288	4	Light traffic wear
	289	5	No wear
	289A	4	Light traffic wear
	289B	4	Light traffic wear
	Hallway Study Area	3	Noticeable wear under desk
	Hallway	4	Light traffic wear
	Front of 302B	4	Light traffic wear

BUILDING	ROOM #	RATING	COMMENTS
MULN	386	3	Noticeable wear under desk
	387	3	Noticeable wear under desk
	391	3	Noticeable wear under desk
	392	3	Noticeable wear under desk
	401	3	Noticeable wear under chairs
	402	4	Light pattern wear
	402A	3	Noticeable wear under chairs
	403	3	Noticeable wear under chair
	486	4	Light traffic wear
	487	4	Light traffic wear
	488	3	Noticeable wear under chairs
	489	3	Noticeable wear under chairs
	490	3	Noticeable wear under chairs
	491	3	Noticeable wear under chairs