



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
PEAH 1 st floor	101	4	
	102	4	
	103	4	
	104	4	
	105	4	
	106	4	
	107	4	
	108	4	
	109	4	
	110	4	
	111	4	
	113	4	
	114	4	
	116	4	
	117	4	
	118	4	
	119	4	
	120	4	
	121	4	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
PEAH	122	4	
	123	4	
	125	4	Computer lab
	127	4	Classroom
2 nd floor	213	4	
	212	4	
	211	4	
	210	4	
	209	4	
	208	4	
	207	4	
	220	4	
	203	4	
	202	4	
	201	4	
	204	4	Classroom
	216	4	
	218	4	
	217	4	
3 rd floor	306	4	
	305	4	
	304	4	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
PEAH	303	4	
	302	4	
	301	4	
	318	4	Classroom
	317	4	Classroom
	307	4	Classroom
	315	4	
	314	4	
	313	4	
	312	4	
	311	4	
	310	4	
	309	4	Classroom