



2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
PHYS	113	3	Traffic lanes and stains
	248	4	A few stains
	242b	5	
	241	3	
	242a	5	
	240	3	Traffic lanes
	239	3	Traffic lanes
	237	4	
	236	3	Traffic lanes
	235	3	Odor present in carpet
	234	3	Worn traffic lanes
	233	3	Traffic lanes
	232	3	Traffic lanes
	231	3	Traffic lanes and stains
	230	4	



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
PHYS	229	5	
	228	3	Traffic lanes
	227	4	
	226	3	Traffic lanes at entrance
	225	4	
	224	3	Traffic lanes and discoloration under desk
	223	4	
	222	3	Under desk has discoloration
	221	3	Under desk has discoloration
	220	4	
	219	4	Slight discoloration under desk
	218	4	
	217	3	Discoloration under desk
	216	4	
	215	3	Traffic lanes and under desk discoloration



UNIVERSITY OF ARKANSAS

BUILDING	ROOM #	RATING	COMMENTS
PHYS	213	4	Slight discoloration under desk
	211	4	
	210	4	
	207	3	Traffic lanes and under desk has discoloration and stains
	206	4	
	204	4	Slight discoloration under desk
	202	3	Discoloration under desk
	201	4	

Alm8/31/12