



## 2016 CARPET CONDITION SURVEY

1. WORN OUT – some places worn through to backing, needs replacement
2. WORN CONDITION – still serviceable, heavy wear in traffic lanes and under chairs
3. AVERAGE – showing some noticeable wear in traffic lanes, under chairs, good condition overall
4. ALMOST NEW – light traffic pattern wear
5. NEW OR LIKE NEW – no wear

BUILDING	ROOM #	RATING	COMMENTS
PTSC Basement	006	5	New
	009	3	
	115	4	
	115B	4	
	116	4	
2 <sup>nd</sup> Floor	217	4	
	217A	4	
	218	4	
	214	3	
	215	4	
	216	4	
3 <sup>rd</sup> Floor	309	4	
	316	4	
	316A	4	