

CARPET CONDITION SURVEY

Stonehenge Apartments - building 2 (STH2)

Last Update Oct 2013

Room #	Rating	Comments
12	1	back only, front n/a
13	3	needs extraction cleaning, back only, front n/a
14	3	back only, front n/a
15	2	reasonably clean, no stains
16	n/a	
17	n/a	
18	2	reasonably clean, no stains
19	2	reasonably clean, no stains
20	3	could use extraction cleaning
21	2	could use extraction cleaning
22	3	could use extraction cleaning, back only, front n/a
23	3	could use extraction cleaning
24	3	front 2, back 3, could use extraction cleaning