

Facilities Management Facility Operations and Maintenance

## **2016 CARPET CONDITION SURVEY**

- 1. WORN OUT some places worn through to backing, needs replacement
- 2. WORN CONDITION still serviceable, heavy wear in traffic lanes and under chairs
- 3. AVERAGE showing some noticeable wear in traffic lanes, under chairs, good condition overall
- 4. ALMOST NEW light traffic pattern wear
- 5. NEW OR LIKE NEW no wear

BUILDING	ROOM #	RATING	COMMENTS
STOS	F26	3	
	F27	3	
	HALLWAY	3	
	HALLWAY	3	