



FY 2015 CARPET CONDITION SURVEY

1. WORN OUT- some places worn through to backing, needs replacement.
2. WORN CONDITION- still serviceable, heavy wear in traffic lanes and under chairs.
3. AVERAGE- showing some noticeable wear in traffic lanes, under chairs, good condition overall.
4. ALMOST NEW- light traffic pattern wear.
5. NEW OR LIKE NEW- no wear.

BUILDING	ROOM #	RATING	COMMENTS
UNHS	001	3	Noticeable wear under chairs
	004	4	Light wear
	107	4	Light wear
	Across from Gearhart Room	4	Light wear
	Hallway, 2 nd Fl.	2	Heavy traffic wear
	202	3	Noticeable wear
	203	3	Noticeable wear
	205	3	Noticeable wear
	206	3	Noticeable wear
	207	3	Noticeable wear
	208	3	Noticeable wear
	209	3	Noticeable wear
	210	3	Noticeable wear
	215	3	Noticeable wear

BUILDING	ROOM #	RATING	COMMENTS
UNHS	216	3	Noticeable wear
	217	3	Noticeable wear
	218	3	Noticeable wear
	219	3	Noticeable wear
	220	3	Noticeable wear
	221	4	Light wear
	222	4	Light wear
	223	3	Noticeable wear
	224	3	Noticeable wear
	226	3	Noticeable wear
	227	3	Noticeable wear
	228	3	Noticeable wear
	Hallway, 3 rd Fl.	2	Heavy traffic wear
	301A	3	Noticeable wear
	301B	3	Noticeable wear
	301C	3	Noticeable wear
	301D	3	Noticeable wear
	301E	3	Noticeable wear
	301F	3	Noticeable wear
	302	3	Noticeable wear
	306	3	Noticeable wear

