

Facilities Management Facility Operations and Maintenance

2016 CARPET CONDITION SURVEY

- 1. WORN OUT some places worn through to backing, needs replacement
- 2. WORN CONDITION still serviceable, heavy wear in traffic lanes and under chairs
- 3. AVERAGE showing some noticeable wear in traffic lanes, under chairs, good condition overall
- 4. ALMOST NEW light traffic pattern wear
- 5. NEW OR LIKE NEW no wear

| ROOM # | RATING | COMMENTS |
|--------|--|--|
| 102 | 5 | |
| 104 | 5 | |
| 106 | 5 | |
| 107 | 5 | |
| 101E | 5 | |
| 101 | 5 | |
| 113 | 5 | |
| 103 | 5 | |
| 117 | 5 | |
| 101 | 5 | |
| 105 | 5 | |
| 107 | 5 | |
| 112 | 5 | |
| 109 | 5 | |
| | 102 104 106 107 101E 101 113 103 117 101 105 107 112 | 102 5 104 5 106 5 107 5 101E 5 101 5 113 5 103 5 117 5 101 5 105 5 107 5 112 5 |



| BUILDING | ROOM # | RATING | COMMENTS |
|----------|--------|--------|----------|
| UTCH | 115 | 5 | |
| | 111 | 5 | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Alm2016/